

(ALASKAN COPPER)

Approval Date: Including Revision

Revision Date: New

Number:

Process:

BURNING TABLE CLEANING

SAFETY EQUIPMENT

Safety T PPE

SPECIAL TOOLS REQUIRED

Cusco vacuum truck
6" Flex hose
20 Yard dewatering roll off box
2" double diaphragm pump
Air Compressor
Pressure Washer

MATERIALS REQUIRED

20'x100' roll of 6 mil plastic sheeting
Flat shovels
Spade shoves
Squeegee
Duct tape
Absorbent pads
Dewatering box filter liner
10 gallons or Treatment Chemical

REQUIRED AND/OR RECOMMENDED PERSONAL PROTECTIVE EQUIPMENT

Gloves Nittrile inner gloves with PVC outer gloves
Shoes Rubber steel toe boots/ leather steel toe boots

Body Tyvek coverall / Saranex Coverall Face Niosh approved safety glasses

Respiration Full face APR with P100 cartridges or equivalent

Other Ear Plugs

BURNING TABLE CLEANING

DRAFT

Rev. 10/26/09 12:58 PM

PAGE 1